

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

June 7, 2011

CERTIFIED RETURN RECEIPT 7009 3410 0001 4203 1829

Jon Young 2402 Broadview Court Sandy, Utah 84092

Subject: Permit Suspension Removed for Failure to Pay Required Permit Fees, Jon Young, Torry Buff

Quarry, S/055/0012, Wayne County, Utah

Dear Mr. Young:

On June 2, 2011, the past due permit fees for the Torry Buff Quarry were paid in full, and the suspension has been removed. You are now authorized to resume mining.

You also had questions about the bond, the need for a bond increase and possible bonds for quarries in Sanpete County that had been transferred. The current bond for the Torry Buff Quarry is \$10,000.00 and is due to be adjusted on May 19, 2012. The bond rates will be adjusted in April 2012, so it is not known what the new bond amount will be. Based on current bonding requirements, the bond increase is expected to be about \$2,600.00 to \$3,000.00.

The only active permit issued by the Division of Oil, Gas and Mining in the name of Jon Young quarry is for the Torry Buff quarry. The Division has no record of any other reclamation sureties in your name. If you have additional information please let us know.

A Division representative inspected the site on April 20, 2011, and found what appears to be a jug of antifreeze and a bucket of hydraulic fluid. Those items are considered deleterious materials and must be removed from the site or stored in a manner that they will not escape into the environment. There was also a significant amount of trash on the site that must be removed. **Please remove the above mentioned items by no later than July 6, 2011**.

If you have questions or concerns regarding this letter, please call Wayne Western at 801-538-5263. Thank you for your prompt response.

Sincerely

Paul B. Baker

Minerals Program Manager

PBB:whw:eb

cc: JBlake@utah.gov

P:\GROUPS\MINERALS\WP\M055-Wayne\S0550012-YoungTorreyBuff\final\Susp-06022011.doc

